


Established 4-6-12
 Pelley-Ladeholtz
 Hollander
 Chief-Chamberlain
 SD. Gladys W. Lind

30-14-5
 N



34 35
 3 2 6-13-40-209-12' x 15' x 10' hole
 in center of lot. No find
 At this location a deep cut was
 apparently destroyed cor. Using
 ties layed out by H.B. Fisher,
 May 1913, S.R. 349 established
 corner. Set C.M. 2657.0 East
 of 1/4 cor. at 2-82-41.17 1/2
 North of center of 5" Cor. post;
 11' east of fence cor. on NW cor.
 of intersection 20'S of line
 of fence from east on N. side
 of road

New
 18.5 NE of 12" burr oak
 17.5 N of cor. post
 56.0 SW of 5" ash
 194.1 WNW of SW cor. Cambridge
 195.0 SW of NW Cor. Cambridge