

34
3

N 1/2 cor sec 5 - T34N R41W

A thorough search failed to reveal cor. Treated cor as obliterated.
Set CM in E of road on 1/4 ft. line
Eg. line is correct according to statements by two witnesses, and has been unchanged for more than 30 years.

CM is 3.1' N of true line bet. sec. cor.

41186 Found Cone. Mon on surface broken off. Replaced with 1" iron rebar 12" deep reled

- Ties from X" nails
- 660 S.E. from Wood Post
- 426 S. from Corner Post
- 586 S.W. from E. Post
- 419 N. from Brace Post
- 489 N.E. from 1st Steel Post W.

3-67
012-9

