

19-20

E 1/2 cor of sec - 19 - B4 - 40

Dug 5' x 10' x 10' hole in line of fence from W. Did not find evidence

See page 33

18/19

8-6-40 Dug 3' x 8' x 10' hole in line with N & S fence no find

Doubled 1/4 1/4 Cor from East & split to road. Established Cor. at this point. Area had been well dug without finding any evidence of old corner. Set C.M. Ties from "X" nails

43.88 S.E. from Gate Post

34.78 S. from Corner Post

47.0 S.W. from Gate Post

33.98 N. from Corner Post

43.85 N.W. from Gate Post

14-40-E

33-7-S

14-4P-S

14-48-S

8-8-56

Richards

W. 1/2 T.

Judges

Cor. 5-11-42

Established 5-12-42

Byge-Hollander, Robert Erickson

Chief Chapman

2/27/91 Set Iron Pin from old ties Sandquist Crew RLS # 4129

