

2-1 E/4 cor Sec 2

4-15-41 Ranchman 25772 N from


All cor sec 11 in quarter of sec. for E/4 cor  
Sec 2. WC 40 ft's of 1/4 cor Sec 2.

Measurements indicate W.N. sec  
well as 1/4 cor fall in Boyer River channel

35 6-19-40 Dug 2'x8'x10' hole on  
2 fence cor. N. find.

4-14-41 Dug 4'x4'x8 hole at  
fence corner intersection.  
Did not find cor This cor  
has been sought for 3 times

30-52-5



Sought 4-14-41  
Resought 4-14-41  
Chief Hughes  
Shives, Bendixen,  
Emge and Turner