FOLLOW UP D
PROOFED
SCANIED

Crawford County Recorder
Denise Meeves
Fee Book 2013-1817
07/29/2013 611:57AM
PLC PLAT CORNER CER
Book: Page: \$7.00 # Pages: 1

WILKE LAND SURVEYING INC.

401 1800th Street

Panama, lowa 51562

(712)489-2898

## UNITED STATES PUBLIC LAND SURVEY CORNER CERTIFICATE


SECTION 6 TOWNSHIP 83N RANGE 38W COUNTY CRAWFORD

Reason for Certificate: (No record Certificate)

Monument Description and Remarks:

NE CORNER NW1/4 SE1/4 — Set 5/8" diameter by 24" rebar with orange cap PLS \$17048 (flush) at the midpoint of the North line of the Southeast Quarter.

SE CORNER SW1/4 SE1/4 — Set 5/8" diameter by 24" rebar with orange cap PLS \$17048 (flush) on the South side of old corner post with fences running North and South. Found old wire grown into trees to the West supporting corner location.



NE CORNER NW1/4 SE1/4 SEC. 6,783N, R38W (Set 5/8" dia. by 24" rebor w/orange cop PLS \$17048, flush with ground)

Ties: 11.35' SE of "X" noils in top of fence division corner post.

2.1' East of existing fence line South.

E1/4 CORNER SEC. 6,T83N, R38W (Fnd. conc. mon. w/brose disc)

2621.99

Ties: 0.32' South of "X" nails in South face of corner post.

7.42" South of "X" noits in South face of brace post.

9.14" North of "X" nalls in blaze on North face of East trunk of a double 12" diameter trunk mulberry tree.

SE CORNER SW1/4 SE1/4 SEC. 6,T83N, R38W (Set 5/8" dis. by 24" rebor w/orange cop PLS #17048, flush with ground)



## \*\*ALL DISTANCES ARE PLUMB\*\*

List Corner	Corners to be Section		Range
NE CORNER NW1/4 SE1/4	6	83N	38W
SE CORNER SW1/4 SE1/4	6	83N	38W

I hereby certify that this land surveying document was prepared and the related survey work use performed by me or under my direct personal supervision and that I am a duly licensed Land Surveyor under the land of the State of Land.

Dean a. Wille

Ulcense number 17048

the Branca recovered data to December 31, 2013

Pages or sheets covered by this seal: This page only