FOLLOW UP 1 PROOFED SCANIED

Crawford County Recorder
Denise Meeves
Fee Book 2013-1817
07/29/2013 611:57AM
PLC PLAT CORNER CER
Book: Page: \$7.00 # Pages: 1

WILKE LAND SURVEYING INC.

401 1800th Street

Panama, lowa 51562

(712)489-2898


UNITED STATES PUBLIC LAND SURVEY CORNER CERTIFICATE

SECTION 6 TOWNSHIP 83N RANGE 38W COUNTY CRAWFORD Reason for Certificate: (No record Certificate)

Monument Description and Remarks:

NE CORNER NW1/4 SE1/4 — Set 5/8" diameter by 24" rebar with orange cap PLS \$17048 (flush) at the midpoint of the North line of the Southeast Quarter.

SE CORNER SW1/4 SE1/4 — Set 5/8" diameter by 24" rebar with orange cap PLS #17048 (flush) on the South side of old corner post with fences running North and South. Found old wire grown into trees to the West supporting corner location.



NE CORNER
NW1/4 SE1/4
SEC. 6,783N, R38W
(Set 5/8" dia. by 24" rebor
w/arange cap PLS \$17048,
flush with ground)

Ties: 11.35' SE of "X" noils in top of fence division corner post.

2.1' East of existing fence line South.

E1/4 CORNER SEC. 6,TB3N, R38W (Fnd. conc. mon. w/bross disc)


2621.99

Ties: 0.32' South of "X" nails in South face of corner post.

7.42" South of "X" noits in South face of brace post.

9.14' North of "X" nafie in blaze on North face of East trunk of a double 12" diameter trunk mulberry tree.

SE CORNER
SW1/4 SE1/4
SEC. 6,T83N, R38W
(Set 5/8" dia. by 24" rebar
w/arange cap Pts \$17048,
flush with ground)



ALL DISTANCES ARE PLUMB

List Corner	Corners to be Section		Range
NE CORNER NW1/4 SE1/4	6	83N	38W
SE CORNER SW1/4 SE1/4	6	83N	38W

I harshy certify that this land surveying document was prepared and the related survey work was performed by one or under my direct personal supervision and that I am a duly licensed Land Surveyor

Dear a. Wilke 7/2

Ucense number 17048

My Rosnes renewed date is December 31, 2013

Tages or sheets covered by this seci: This page only