

25 30	Found rock 10" x 5" 13" rotted remains of wood stake at a depth of 3" Lowered same to a depth of 4' and set C.M.		
	Ties from x-sps		
	308 E from car post		
	393 S.E. in 1st steel post		
	381 S.W. in 1st steel post	6-10-71	
	342 W in 1st steel post	Instr. Ties	
	2x2" Tacked Hubs	(Krusc)	
	100.0'	Checked & Retired	
	2x2" Tacked Hubs	100.0'	5-273 Cue
	25		
	Dug hole 5' x 12' x 16'	Did not find air	
	Found partly decayed painted 2x2x16' oak stake 16" below surface. Lowered evidence and set C.M. one foot below surface		
	Ties:		
	308 S from x-spikes in 8' round car post		
	300 N from x-spikes in 8' creosote car post		
	744 NE from 1st steel post west		
	618 N from 1st cedar post south		

