Crawford County Recorder
Denise Meeves
Fee Book 2012-0088
01/12/2012 @11:15AM
PIC PLAT CORNER CER
Book: Page: \$7.00
Total Fees: \$7.00

ELLOYED FALLOY UP ELLOYED STANKED

| Prepared by: Nathan  | H. Cartson Address:   | 3701 12th Street N. Sul   | te 206, Phone   | 320-253-9495       |
|--|---|---------------------------|-----------------|--------------------|
| UNITED STATES PUBLIC LAND SURVEY CORNER CERTIFICATE FOR  |   |                           |                 |                    |
| Land survey monume   | nts situated in Section17   | Townshi                   | p . 85N         |                    |
| Rang   | c 39W of the Fr   | fth Principal Meridian, _ | Crawford        | County, Iowa.      |
| · Previously recorded in   | o   |                           | in County l     | Recorder's Office. |
| (Show reason for preparing this certificate, the evidence and detailed procedures used in establishing the corner positions & measurements found or placed.)           |   |                           |                 |                    |
| MONUMENT DESCRIPTION AND REMARKS: Notes from Westwood Professional Services, Inc. in 2006  |   |                           |                 |                    |
| indicate that 5'x10' by 3.5' deep hole was excavated and a monument in broken concrete was found.  |   |                           |                 |                    |
| A 3/8" rebar with LS Cap 13721 was placed above the concrete monument. In November of 2011   |   |                           |                 |                    |
| I searched the area and found a 3/8" rebar with LS cap 13721 in the centerline of the road   |   |                           |                 |                    |
| 3 feet north of a fence line to the east. Accepted monument as marking the corner position and   |   |                           |                 |                    |
| established reference ties as noted below.   |   |                           |                 |                    |
|  |   |                           | _ <del>_</del>  |                    |
|  | <del> </del>  |                           | <del> </del>    | <del></del>        |
|  |   |                           |                 |                    |
|  |   |                           |                 |                    |
| PLAN — VIEW  (Show a minimum of three reference ties to durable physical objects, relevant monuments and physical conditions that will enable recovery of the corner.) |   |                           |                 |                    |
|  | 1.1   | Ę.                        |                 |                    |
|  | *   | *                         | Г               | <del></del>        |
|  | *   | i                         | Ļ               |                    |
| <u>    ξ                                 </u>  |   |                           |                 |                    |
| 7 2  |   |                           |                 |                    |
| × × × ×   3  |   |                           |                 |                    |
|  |   |                           |                 |                    |
|  |   |                           |                 |                    |
| C AVE  |   |                           |                 |                    |
| C AVE  |   |                           |                 |                    |
|  |   |                           |                 |                    |
| Wood Post  |   |                           |                 |                    |
| ¥!    <b>*</b>   |   |                           |                 |                    |
|  |   |                           |                 |                    |
| k ₹  |   |                           |                 |                    |
|  |   |                           |                 |                    |
|  | 1 • 1   | 1 . 1                     |                 |                    |
|  |   |                           |                 |                    |
| SEAL   | I hereby certify that this land surveying<br>and the related survey work was perfor |                           | Comers to 1     | e incexed          |
| HILLAND WALL   | direct personal supervision and that I a<br>Surveyor under the laws of the State of |                           | Corners Section | Twp. Range         |
| See College  | Screey or moder one news or the Scale or lows. NE 17 85N 39W                        |                           |                 |                    |
| NATHAN ME Och W. Oh 1/4/2012   |   |                           |                 |                    |
| CARLSON O Signature Date   |   |                           |                 |                    |
| NATHAN CARLSON 19314   | Typed/Printed Name: Nathan H.   | Carlson                   |                 |                    |
| TOWA WITH  | License Number: 19314   | 2012                      |                 |                    |
|  | My license renewal date is December 31, 2012  |                           |                 |                    |
|  | Pages or sheets covered by this seal: _   | I his sheet               |                 |                    |
| et et 2 me   | i   |                           |                 |                    |