

UNITED STATES PUBLIC LAND SURVEY CORNER CERTIFICATE

OF

Land Survey Monuments situated in Section 1, Township 85, Range 39, of the Fifth Principal Meridian, Crawford County, Iowa. Previously recorded in does not apply in County Recorder's Office.

(book, page, document number, etc.)

(Show reason for preparing this certificate, the evidence and detailed procedures used in establishing the corner positions and monumentation found or placed.)


Monument Description and Remarks: as described below

PLAN - VIEW

(Show a minimum of three reference ties to durable physical objects, relevant monuments and physical conditions that will enable recovery of the corner.)

A. West 1/4 corner concrete monument located 42" deep. Set 24' x 5/8" diameter iron bar over monument.

- x-nails in power pole SE 38.65'
- NW corner of elec. box SE 33.05'
- iron bar 33.00' east on R.O.W.
- steel fence post NW 36.00'



B. SW corner of SW 1/4 - located 1" iron bar 10" deep.

- x-nails in power pole SE 85.25'
- x-nails in corner post SE 56.20'
- x-nails in corner post SW 56.45'
- x-nails in top of corner post SW 56.80'
- x-nails in power pole SW 69.90'



I hereby certify that the survey work was completed and this certificate was prepared by me or under my direct personal supervision and that I am a duly registered land surveyor under the laws of the state of Iowa.

Signature: Bud L. Vote
Name typed or printed: Bud L. Vote

Date: February 5, 1993 Reg. No. 7718

SEAL



Corners	List Corners to be Indexed		
	Section	Twp	Range
W 1/4	1	85	39
SW	"	"	"

FILED DENISON, IOWA
CRAWFORD COUNTY

93 FEB 12 AM 10:13

INST. NO. 93-0368
DENISE JURGENSEN, RECORDER
Denise Jurgensen
FEE 5.00

INDEXED MG
FOLLOW UP _____
PROOFED _____