## UNITED STATES PUBLIC LAND SURVEY CORNER CERTIFICATE OF

LAND SURVEY MONUMENT SITUATED IN SECTION	
MONUMENT DESCRIPTION AND REMARKS  N1/4 CORNER - FOUND WOOD STAKE 6" DEEP OVER CM 4' DEEP REPLACED EVIDENCE AND SET 5/8" IRON PIN W/CAP #8893 6" DEEP  NE CORNER - FOUND 5/8" IRON PIN W/RIBBON 6" DEEP	
PLAN VIEW SHOWING RELATIVE LOCATION OF MONUMENT	AND REFERENCE POINTS.
	1 1

48.45 TOP CTR. TELE. PED. 'X' NAILS IN 'X' NAILS IN COR. POST HOUSE FACE SLOPE CHAINED DISTANCES

39.5 'X' NAILS IN PWR. POLE TOP CTR. TELE. PED.⊘ 'X' NAILS IN BRACE POST 'X' NAILS IN BRACE POST 'X' NAILS IN BRACE POST SLOPE CHAINED DISTANCES

N1/4 CORNER SECTION 5-85-39

NE CORNER SECTION 5-85-39

I HEREBY CERTIFY THAT THE SURVEY WORK WAS COMPLETED AND THIS LAND SURVEYING DOCUMENT WAS PREPARED BY ME OR UNDER MY DIRECT PERSONAL SUPERVISION AND THAT I AM A DULY LICENSED LAND SURVEYOR UNDER THE LAWS OF THE STATE OF IOWA.

NOV 2 2 1996

DATE

TERENCE E. CRAWFORD

IA LICENSE NO. 8893 EXP. DATE DECEMBER 31, 1997

SE PROJECT NO. 2526

SUNDQUIST ENGINEERING, P.C. 120 SOUTH MAIN, P.O. BOX 220 DENISON, IOWA 51442 PH. (712)263-8118

RECORDING OFFICER

FILED DENISON, IOWA CRAWFURD COUNTY

96 NOV 26 AM 10: 06

FOLLOW UP A PROOFED -