
## UNITED STATES PUBLIC LAND SURVEY CORNER CERTIFICATE **OF**

LAND SURVEY MONUMENT SITUATED IN SECTION5, T THE 5TH P.M.,CRAWFORDCOUNTY, IOWA. PREVIOUSLY RECORDED IN BOOK, PAGE, OT	
MONUMENT DESCRIPTION AND REMARKS	<del>\</del>
W1/4 CORNER - FOUND WOOD STAKE AND BRICK 20" DEEP OVER CM 2' DEEP, SET 5/8" IRON PIN W/CAP #8893 6" DEEP OVER CM	<b></b>
E1/4 CORNER - SET 5/8" IRON PIN W/CAP #8893 FLUSH WITH GROUND, SET BETWEEN TWO CORNER POSTS EILEEN STRECK SAID AREA WAS LEVELED AFTER ROAD.	
WAS ABANDONED AND POSTS WERE SET ON CORNER	

PLAN VIEW SHOWING RELATIVE LOCATION OF MONUMENT AND REFERENCE POINTS.



I HEREBY CERTIFY THAT THE SURVEY WORK WAS COMPLETED AND THIS LAND SURVEYING DOCUMENT WAS PREPARED BY ME OR UNDER MY DIRECT PERSONAL SUPERVISION AND THAT I AM A DULY LICENSED LAND SURVEYOR UNDER THE LAWS OF THE STATE OF IOWA:

NOV 2 2 1996

DATE

TERENCE E. CRAWFORD

IA LICENSE NO. 8893 EXP. DATE DECEMBER 31, 1997

SE PROJECT NO. 2526

SUNDQUIST ENGINEERING, P.C. 120 SOUTH MAIN, P.O. BOX 220 DENISON, IOWA 51442 PH. (712)263-8118

RECORDING OFFICER

FILED DEMISON, IOWA CRAWFORD COUNTY

'X' NAILS TOP BRACE POST

96 NOV 26 AH 10: 09

INDEXED FOLLOW UP PRUOFED -