PROSTED AAN
FOLLOW UP
PROSTED
SOWHAD

Instrument #: 2015-2165
10/15/2015 09:03:19 AM Total Pages 1
PLC PLAT CORNER CER
Recording Fee: \$7.00 Transfer Tax: \$0
Denise Neeves, Recorder, Crawford County Iowa

WILKE LAND SURVEYING INC.

401 1800th Street

Panama, lowa 51562

(712)489-2898


UNITED STATES PUBLIC LAND SURVEY CORNER CERTIFICATE


SECTION 11 TOWNSHIP 82N RANGE 40W COUNTY CRAWFORD

Reason for Certificate: Survey in W1/2 NW1/4

Monument Description and Remarks:

W1/4 CORNER — Found carriage bolt in asphalt pavement using the corner certificate by PLS #14808 recorded as Inst. No. 2006-0558 at the Crawford County Recorder's Office. Some of the ties appear to have been copied from PLS #6806 certificate recorded as Inst. No. 2001-2942, and do not fit the carriage bolt location. The carriage bolt was used on my previous survey of record as Inst. No. 2007-0052, but was mistakenly labeled the as being a lead plug. Now after tieing in to PLS #6806 surveys of record as Inst. Nos. 2001-2939 & 2004-1107, I found that the carriage bolt appears to have been set in error after the highway asphalt overlay project in 2005. I remonumented the Corner with a MAG Nail using found monuments and data from PLS #6806 survey of record as Inst. No. 2001-2939. See my survey of Lot 3 of the W1/2 W1/2 NW1/4 for monuments and data used to calculate the monument location. The set MAG Nail is 2.54' Southeast of the found carriage bolt.





DEAN A. WILKE 17048

ALL DISTANCES ARE HORIZONTAL

List Cor	ners to be l		
Corner	Section	Twp.	Range
W1/4 CORNER	11	82N	40W

I hereby certify that this land surveying document was prepared and the related survey work was performed by me or under my direct personal supervision and that I am a duly licensed Land Surveyor under the laws of the State of lows.

Dean a. Wilke 10/14/15

License number 17048

My ficense renewal date is December 31, 2015

Pages or sheets covered by this seak This page only