INDEXED FOLLOW UP **PROOFED** SCANNED

Instrument #: 2019-2225
11/25/2019 02:40:45 PM Total Pages: 1
PLG PLAT COR CERT
Recording Fee: \$7.00 Transfer Tax: \$0
Denise Meeves, Recorder, Crawford County Iowa

BYY'L BOOK HITTLE IN ALEXANDER (NAME IN A SANDER)

WILKE LAND SURVEYING INC.

401 1800th Street

Panama, Iowa 51562

UNITED STATES PUBLIC LAND SURVEY CORNER CERTIFICATE


SECTION 17 TOWNSHIP 82N RANGE 40W COUNTY Crawford


Reason for Certificate: Survey in the SE1/4 NW1/4

Monument Description and Remarks:

N1/4 CORNER — The record monument was destroyed by the paving of Nelson Park Road. Reset a chiseled "X" in the concrete pavement using ties from the record PLS #8893 Corner Certificate being Inst. No. 2012-0635 at the Crawford County Recorder's Office.

CENTER - Set a 5/8" diameter by 24" long rebar with a green cap PLS #24091 (0.5' deep) using the found North monuments and data from a PLS #5798 survey of Lot 1 of the NE1/4 SW1/4 dated 9/10/1969 and found in the Crawford County Auditor's Office vault. The monument fits well with the centerline of 2 Mile Road and the fence line West.






4.7' West of concrete

E NELSON PARK ROAD

centerline joint. N1/4 CORNER

(Record monument destroyed by paving. Reset chiseled "X" in concrete pavement using record ties.)

ALL DISTANCES ARE HORIZONTAL



10WA
#24091 GANULE
GA. WIL

List Corners to be Indexed Corner Section Twp. Range 40W N1/4 CORNER 17 82N 17 82N 40W CENTER

I hereby certify that this land surveying document was prepared and the related survey work was performed by me or under my direct personal supervision and that I am a duly licensed Land Surveyor under the laws of the State of lowa.

25/2019

License number 24091

My license renewal date is December 31, 2020

Pages or sheets covered by this seal: This page only