PROOFED

## Crawford County Recorder Denise Meeves Fee Book 2010-0928

Penise Book 2010 Fee Book 2010 05/10/2010 010:36AM 2LC FLAT CORNER CER Page: \$9.00

# Pages: 1

WILKE LAND SURVEYING INC

401 1800th Street


Panama, lowa 51562

## UNITED STATES PUBLIC LAND SURVEY CORNER CERTIFICATE

SECTION 30 TOWNSHIP 82N RANGE 39W COUNTY CRAWFORD Certificate Prepared For: NO RECORD CORNER CERTIFICATES

## Monument Description and Remarks:

- (1)- All tie points were still there referenced in the field mi tie points were still there referenced in the field book at the Crawford County Engineer's Office. The iron pin w/cap set by PLS #4129 in 1992 was gone but dug and found a 60d nail with flagging. Replaced nail with 5/8" dia. by 24" rebar w/orange cap PLS # 17048 (0.9' deep) in dirt road.
- (2) No record of a monument at this corner at the Crawford County Engineer's Office. Dug and probed around the fence intersection point. Nothing found. Set 5/8" dia. by 24" rebor w/orange cap PLS #17048 (flush) at the intersection of fences: West, North, and South.



NOTE: After a survey was done on a parcel of land in the SW1/4 NE1/4 the client cancelled the survey and didn't want it recorded.





I hereby certify that this land surveying document was prepared and the related survey work was performed by me or under my direct personal supervision and that I am a duly licensed Land Surveyor under the laws of the State of lowa.

License number 17048

My license renewal date is December 31, 2011

Pages or sheets covered by this seal: This page only





List	Corners to be Indexed		
Corner	Section	Twp.	Range
N1/4 CORNER	30	82N	39W
E1/4 CORNER	30	82N	39W